

HY-VO® Chain Discontinuation & Replacement

HV523 replacing HV091

Effective immediately the HV091 HY-VO® chain will no longer be available. It is being replaced in the aftermarket by the HV523 (released January 2019).

- Chains are dimensionally the same - details below
- HV523 has better NVH characteristics (less noise)



Part #: **HV523**
OE Part #: DCS 1221271 / DCS 8221271

Applications:

- Mercedes M-Class (1-Speed) 2003+
- Mercedes ML500 / B-SUV's (1-Speed) 2015+

Dimensions:

Pitch (in)	Width (in)	Length	Joint Type
0.375"	1.50"	84P	Rocker

