

Ford 4R100 Friction Plate Kit Discontinuation & New Kit Introduction

September 2020

Effective immediately the 34047KIT friction plate kit (1998-2000) will no longer be available. A new kit for the 4R100 is being introduced to cover model years 2001+.

- The Intermediate plate in the 35721KIT is high-energy as opposed to the 34047KIT



Year: 2001+
BW Part #: 35721KIT

Position	KIT Qty
Overdrive	3
Intermediate	3
Direct	5
Forward	4
Reverse	6
Coast	3

 **BorgWarner**

ts.aftermarket.borgwarner.com